

0 226152



**THE PORT AUTHORITY** OF NY & NJ

September 13, 2011

United States Environmental Protection Agency  
Air Compliance Branch  
290 Broadway, 21st Floor  
New York, NY 10007-1866

Attn: NESHAPS COORDINATOR

RE: TETERBORO AIRPORT – BUILDING # 27, GROUND FLOOR, FLOOD  
DAMAGED KITCHEN AREA  
CONTRACT # MFA-909.021, OPERATOR PROJECT # 909.013, W.O. #13

Dear Madam/Sir:

Our RACM and NON-RACM project courtesy notification for work to be done at the above referenced location is attached.

If you have any questions please contact me at (201) 595-4881.

Sincerely,

Uday Mehta, Manager  
Environmental Field Operations  
Construction Management Division

cc: Project File (EPA-2104)  
RACM Notification File

UM/dc

**U.S. Environmental Protection Agency  
Notification of Demolition and Renovation**

Operator Project #: 909.013		Postmark:		Date Received:		Notification #: EPA-2104	
I. Type of Notification (O=Original R=Revised C=Canceled) O							
II. Facility Information (Identify owner, removal contractor, and other operator)							
Owner Name: THE PORT AUTHORITY OF NY & NJ							
Address: 241 ERIE ST. ROOM 236							
City: JERSEY CITY				State: NJ		Zip: 07310	
Contact: R. CAMPIONE, FACILITY SUPERVISOR, ASBESTOS OPS						Telephone: (973) 624-6898	
Removal Contractor: B & N & K RESTORATION CO. INC.							
Address: 223 RANDOLPH AVENUE							
City: CLIFTON				State: NJ		Zip: 07011	
Contact: G. ROGER WOODMAN						Telephone: (973) 478-4681	
Other operator: N/A							
Address:							
City:				State:		Zip:	
Contact:						Telephone:	
III. Type of Operation (D=Demo O=Ordered Demo R=Renovation E=Emergency) R							
IV. Is Asbestos Present? (Yes/No) YES							
V. Facility Description (include building name, number, floor, and /or room number):							
Building Name: TETERBORO AIRPORT							
Address: 399 INDUSTRIAL AVENUE							
City: TETERBORO				State: NJ		County: BERGEN	
Site Location: BUILDING # 27, GROUND FLOOR, FLOOD DAMAGED KITCHEN AREA							
Building Size: 100' X 32' X 12'				# of Floors: 1		Age in Years: 45+	
Present Use: AIRPORT OPERATIONS				Prior Use: AIRPORT OPERATIONS			
VI. Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material: BULK SAMPLING UTILIZING PLM METHODS							
VII. Approximate Amount of Asbestos, Including:					Nonfriable Asbestos Materials Not To Be Removed		Indicate Measurement
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed			Non-RACM To Be Removed	RACM to Be Removed	Cat I	Cat II	
Pipes MOLDED BLOCK				20			Lnft: 20
Surface Area FLOOR TILE, MASTIC			956				Sqft: 956
Vol RACM Off Facility Component							Cuft: 0
VIII. Scheduled Dates Asbestos Removal				Start: 09/16/2011		Complete: 10/28/2011	
IX. Scheduled Dates Demo/Renovation				Start:		Complete:	

**U.S. Environmental Protection Agency  
Notification of Demolition and Renovation**

**X. Description of Planned Demolition or Renovation Work, and Method(s) to Be Used:**

N/A

**XI. Description of Work Practices and Engineering Controls to Be Used to Prevent Emissions Of Asbestos  
At the Demolition And Renovation Site:**

GENERAL ISOLATION NON-FRIABLE REMOVAL WITH WET METHODS AND NEGATIVE PRESSURE

**XII. Waste Transporter #1**

**Name:** JIMMY BYRNE TRUCKING

**Address:** 1199 RANDALL AVENUE

**City:** BRONX

**State:** NY

**Zip:** 10474

**Contact:** EVE BYRNE

**Telephone:** (718) 617-0771

**Waste Transporter #2**

**Name:** N/A

**Address:**

**City:**

**State:**

**Zip:**

**Contact:**

**Telephone:**

**XIII. Waste Disposal Site**

**Name:** MINERVA ENTERPRISES INC.

**Location:** 9000 MINERVA ROAD SOUTH EAST

**City:** WAYNESBURG

**State:** OH

**Zip:** 46688

**Telephone:** (330) 866-3435

**XIV. If Demolition Ordered By a Government Agency, Please Identify the Agency Below**

**Name:** N/A

**Title:** N/A

**Authority:** N/A

**Date of Order:** N/A

**Date Ordered To Begin:** N/A

**XV. For Emergency Renovations**

**Date and Hour of Emergency:** N/A

**Description of Sudden or Unexpected Event:**

N/A

**Explanation of How the Event Caused Unsafe Conditions or Would Cause Equipment Damage or an Unreasonable Financial Burden:**

N/A

**XVI. Descriptions of Procedures to Be Followed in the Event That Unexpected Asbestos Is Found or Previously Nonfriable  
Asbestos Material Becomes Crumbled, Pulverized or Reduced to Powder:**

IMMEDIATE ISOLATION OF THE AREA AND ADEQUATE WETTING OF ASBESTOS MATERIAL FOLLOWED BY HEPA VACUUMING AND WET WIPING ALL AFFECTED AREAS

**XVII. I Certify That an Individual Trained in the Provisions of This Regulation (40 CFR Part 61, Subpart M) Will Be On-Site During the Demolition or Renovation And Evidence That the Required Training Has Been Accomplished by This Person Will Be Available for inspection**

(Signature of Owner/Operator)

(Date)

**XVIII. I Certify That the Above Information Is Correct.**

(Signature of Owner/Operator)

(Date)